

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

Inventor(s): Goodall, *et al.*  
Assignee: Cisco Technology, Inc.  
Patent No: 6,940,843  
Issue Date: September, 6, 2005  
Application No.: 10/700,011  
Filed: November 3, 2003  
Title: SELECTING AN ACCESS POINT  
ACCORDING TO A MEASURE OF  
RECEIVED SIGNAL QUALITY

**REQUEST FOR CERTIFICATE OF CORRECTIONS**

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Dear Commissioner:

The above patent contains significant error(s) as indicated on the attached Certificate of Correction form (submitted in duplicate).

X Such error(s) arose through the fault of applicant(s). Please note that such error is of clerical error or minor nature and occurred in good faith and therefore issuance of the Certificate of Correction is respectfully requested.

The fee is being paid herewith by credit card via EFS-Web. The Commissioner is authorized to charge Deposit Account No. 50-0292 for any missing fee. A duplicate of this request is attached.

**Such error(s) specifically:**

In FIG. 6, in the first line of block 615, change "At an EVM-capable" to --At an EVM-capable--.

The undersigned requests being contacted at (510) 547-3378 if there are any questions or clarifications, or if there are any problems with issuance of the Certificate of Correction.

Respectfully Submitted,

July 16, 2008

Date

/Dov Rosenfeld/#38687

Dov Rosenfeld, Reg. No. 38687  
Practitioner of Record.

Address for correspondence:

Dov Rosenfeld  
5507 College Avenue, Suite 2,  
Oakland, CA 94618  
Tel. (510) 547-3378; Fax: (510) 291-2985

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

---

Inventor(s): Goodall, <i>et al.</i> Assignee: Cisco Technology, Inc. Patent No: 6,940,843 Issue Date: September, 6, 2005 Application No.: 10/700,011 Filed: November 3, 2003 Title: SELECTING AN ACCESS POINT ACCORDING TO A MEASURE OF RECEIVED SIGNAL QUALITY	
---	--

---

**REQUEST FOR CERTIFICATE OF CORRECTIONS**

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Dear Commissioner:

The above patent contains significant error(s) as indicated on the attached Certificate of Correction form (submitted in duplicate).

X Such error(s) arose through the fault of applicant(s). Please note that such error is of clerical error or minor nature and occurred in good faith and therefore issuance of the Certificate of Correction is respectfully requested.

The fee is being paid herewith by credit card via EFS-Web. The Commissioner is authorized to charge Deposit Account No. 50-0292 for any missing fee. A duplicate of this request is attached.

**Such error(s) specifically:**

In FIG. 6, in the first line of block 615, change "At an EVM-capable" to --At an EVM-capable--.

The undersigned requests being contacted at (510) 547-3378 if there are any questions or clarifications, or if there are any problems with issuance of the Certificate of Correction.

Respectfully Submitted,

---

July 16, 2008

Date

---

/Dov Rosenfeld/#38687

Dov Rosenfeld, Reg. No. 38687  
Practitioner of Record.

Address for correspondence:

Dov Rosenfeld  
5507 College Avenue, Suite 2,  
Oakland, CA 94618  
Tel. (510) 547-3378; Fax: (510) 291-2985

(Also Form PTO-1050)

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

PATENT NO : 6,940,843

DATED : September 6, 2005

INVENTOR(S) : Goodall, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

In FIG. 6, in the first line of block 615, change "At an EVM-capable" to --At an EVM-capable--

MAILING ADDRESS OF SENDER (Atty/Agent of Record):

Dov Rosenfeld, Reg. No. 38687  
5507 College Avenue, Suite 2  
Oakland, CA 94618

PATENT NO: 6,940,843  
No. of additional copies